

Hundredths of an Inch	0	1	2	3	4	5	6	7	8	9
	0	0.254	0.508	0.762	1.016	1.270	1.524	1.778	2.032	2.286
10	2.54	2.794	3.048	3.302	3.556	3.810	4.064	4.318	4.572	4.826
20	5.08	5.334	5.588	5.842	6.096	6.350	6.604	6.858	7.112	7.366
30	7.62	7.874	8.128	8.382	8.636	8.890	9.144	9.398	9.652	9.906
40	10.16	10.414	10.668	10.922	11.176	11.430	11.684	11.938	12.192	12.446
50	12.7	12.954	13.208	13.462	13.716	13.970	14.224	14.478	14.732	14.986
60	15.24	15.494	15.748	16.002	16.256	16.510	16.764	17.018	17.272	17.526
70	17.78	18.034	18.288	18.542	18.796	19.050	19.304	19.558	19.812	20.066
80	20.32	20.574	20.828	21.082	21.336	21.590	21.844	22.098	22.352	22.606
90	22.86	23.114	23.368	23.622	23.876	24.130	24.384	24.638	24.892	25.146