

| Clear Opening or Space | | Diameter of Rod or Wire | | Steel Weight* Lbs. per Sq. Ft. | Open Area |
|------------------------|------------|-------------------------|------------|--------------------------------|-----------|
| Inch | Millimeter | Inch | Millimeter | | |
| 4 | 101.6 | 1 | 25.40 | 13.06 | 64.00% |
| 4 | 101.6 | 3/4 | 19.05 | 7.68 | 70.90% |
| 4 | 101.6 | 11/16 | 17.46 | 6.53 | 72.80% |
| 4 | 101.6 | 5/8 | 15.88 | 5.46 | 74.80% |
| 4 | 101.6 | 9/16 | 14.29 | 4.47 | 76.90% |
| 4 | 101.6 | 1/2 | 12.70 | 3.58 | 79.00% |
| 4 | 101.6 | 7/16 | 11.11 | 2.77 | 81.30% |
| 4 | 101.6 | 3/8 | 9.53 | 2.07 | 83.60% |
| 4 | 101.6 | 5/16 | 7.94 | 1.45 | 86.00% |
| 4 | 101.6 | .283 | 7.19 | 1.20 | 87.20% |
| 4 | 101.6 | .263 | 6.68 | 1.04 | 88.00% |
| 4 | 101.6 | .250 | 6.35 | .94 | 88.60% |
| 3-3/4 | 95.25 | 1 | 25.40 | 13.77 | 62.30% |
| 3-3/4 | 95.25 | 3/4 | 19.05 | 8.11 | 69.40% |
| 3-3/4 | 95.25 | 11/16 | 17.46 | 6.90 | 71.40% |
| 3-3/4 | 95.25 | 5/8 | 15.88 | 5.77 | 73.50% |
| 3-3/4 | 95.25 | 9/16 | 14.29 | 4.74 | 75.70% |
| 3-3/4 | 95.25 | 1/2 | 12.70 | 3.79 | 77.90% |
| 3-3/4 | 95.25 | 7/16 | 11.11 | 2.94 | 80.20% |
| 3-3/4 | 95.25 | 3/8 | 9.53 | 2.19 | 82.60% |
| 3-3/4 | 95.25 | 5/16 | 7.94 | 1.54 | 85.20% |
| 3-3/4 | 95.25 | .283 | 7.19 | 1.27 | 86.50% |
| 3-3/4 | 95.25 | .263 | 6.68 | 1.11 | 87.30% |
| 3-3/4 | 95.25 | .250 | 6.35 | 1.00 | 87.90% |
| 3-1/2 | 88.90 | 1 | 25.40 | 14.57 | 60.50% |
| 3-1/2 | 88.90 | 3/4 | 19.05 | 8.60 | 67.80% |
| 3-1/2 | 88.90 | 11/16 | 17.46 | 7.32 | 69.90% |
| 3-1/2 | 88.90 | 5/8 | 15.88 | 6.13 | 72.00% |
| 3-1/2 | 88.90 | 9/16 | 14.29 | 5.03 | 74.30% |
| 3-1/2 | 88.90 | 1/2 | 12.70 | 4.03 | 76.60% |
| 3-1/2 | 88.90 | 7/16 | 11.11 | 3.13 | 79.00% |
| 3-1/2 | 88.90 | 3/8 | 9.53 | 2.33 | 81.60% |
| 3-1/2 | 88.90 | 5/16 | 7.94 | 1.65 | 84.30% |
| 3-1/2 | 88.90 | .283 | 7.19 | 1.36 | 85.60% |
| 3-1/2 | 88.90 | .263 | 6.68 | 1.18 | 86.50% |
| 3-1/2 | 88.90 | .250 | 6.35 | 1.07 | 87.10% |
| 3-1/2 | 88.90 | .225 | 5.72 | .87 | 88.30% |
| 3-1/2 | 88.90 | .207 | 5.26 | .74 | 89.10% |
| 3-1/4 | 82.55 | 1 | 25.40 | 15.47 | 58.50% |
| 3-1/4 | 82.55 | 3/4 | 19.05 | 9.16 | 66.00% |
| 3-1/4 | 82.55 | 11/16 | 17.46 | 7.80 | 68.10% |
| 3-1/4 | 82.55 | 5/8 | 15.88 | 6.54 | 70.30% |
| 3-1/4 | 82.55 | 9/16 | 14.29 | 5.37 | 72.60% |
| 3-1/4 | 82.55 | 1/2 | 12.70 | 4.31 | 75.00% |
| 3-1/4 | 82.55 | 7/16 | 11.11 | 3.35 | 77.60% |
| 3-1/4 | 82.55 | 3/8 | 9.53 | 2.50 | 80.40% |
| 3-1/4 | 82.55 | 5/16 | 7.94 | 1.76 | 83.20% |
| 3-1/4 | 82.55 | .283 | 7.19 | 1.46 | 84.60% |
| 3-1/4 | 82.55 | .263 | 6.68 | 1.26 | 85.60% |
| 3-1/4 | 82.55 | .250 | 6.35 | 1.15 | 86.20% |
| 3-1/4 | 82.55 | .225 | 5.72 | .93 | 87.50% |
| 3-1/4 | 82.55 | .207 | 5.26 | .79 | 88.40% |
| 3-1/4 | 82.55 | .192 | 4.88 | .69 | 89.20% |
| 3 | 76.20 | 1 | 25.40 | 16.50 | 56.30% |
| 3 | 76.20 | 3/4 | 19.05 | 9.79 | 64.00% |
| 3 | 76.20 | 11/16 | 17.46 | 8.35 | 66.20% |
| 3 | 76.20 | 5/8 | 15.88 | 7.00 | 68.50% |
| 3 | 76.20 | 9/16 | 14.29 | 5.76 | 70.90% |
| 3 | 76.20 | 1/2 | 12.70 | 4.62 | 73.50% |
| 3 | 76.20 | 7/16 | 11.11 | 3.59 | 76.20% |
| 3 | 76.20 | 3/8 | 9.53 | 2.68 | 79.00% |
| 3 | 76.20 | 5/16 | 7.94 | 1.90 | 82.00% |
| 3 | 76.20 | .283 | 7.19 | 1.57 | 83.50% |
| 3 | 76.20 | .263 | 6.68 | 1.36 | 84.50% |
| 3 | 76.20 | .250 | 6.35 | 1.23 | 85.20% |
| 3 | 76.20 | .225 | 5.72 | 1.01 | 86.50% |
| 3 | 76.20 | .207 | 5.26 | .86 | 87.50% |
| 3 | 76.20 | .192 | 4.88 | .74 | 88.30% |
| 3 | 76.20 | .177 | 4.50 | .63 | 89.20% |
| 3 | 76.20 | .162 | 4.11 | .53 | 90.00% |

| | | | | | |
|-------|-------|-------|-------|-------|--------|
| 2-3/4 | 69.85 | 1 | 25.40 | 17.67 | 53.70% |
| 2-3/4 | 69.85 | 3/4 | 19.05 | 10.52 | 61.70% |
| 2-3/4 | 69.85 | 11/16 | 17.46 | 8.98 | 64.00% |
| 2-3/4 | 69.85 | 5/8 | 15.88 | 7.54 | 66.40% |
| 2-3/4 | 69.85 | 9/16 | 14.29 | 6.20 | 68.90% |
| 2-3/4 | 69.85 | 1/2 | 12.70 | 4.98 | 71.60% |
| 2-3/4 | 69.85 | 7/16 | 11.11 | 3.88 | 74.40% |
| 2-3/4 | 69.85 | 3/8 | 9.53 | 2.90 | 77.40% |
| 2-3/4 | 69.85 | 5/16 | 7.94 | 2.05 | 80.60% |
| 2-3/4 | 69.85 | .283 | 7.19 | 1.70 | 82.20% |
| 2-3/4 | 69.85 | .263 | 6.68 | 1.48 | 83.30% |
| 2-3/4 | 69.85 | .250 | 6.35 | 1.34 | 84.00% |
| 2-3/4 | 69.85 | .225 | 5.72 | 1.09 | 85.40% |
| 2-3/4 | 69.85 | .207 | 5.26 | .93 | 86.50% |
| 2-3/4 | 69.85 | .192 | 4.88 | .80 | 87.40% |
| 2-3/4 | 69.85 | .177 | 4.50 | .69 | 88.30% |
| 2-3/4 | 69.85 | .162 | 4.11 | .58 | 89.20% |
| 2-3/4 | 69.85 | .148 | 3.76 | .48 | 90.00% |
| 2-1/2 | 63.5 | 1 | 25.40 | 19.02 | 51.00% |
| 2-1/2 | 63.5 | 3/4 | 19.05 | 11.37 | 59.20% |
| 2-1/2 | 63.5 | 11/16 | 17.46 | 9.71 | 61.50% |
| 2-1/2 | 63.5 | 5/8 | 15.88 | 8.16 | 64.00% |
| 2-1/2 | 63.5 | 9/16 | 14.29 | 6.72 | 66.60% |
| 2-1/2 | 63.5 | 1/2 | 12.70 | 5.41 | 69.40% |
| 2-1/2 | 63.5 | 7/16 | 11.11 | 4.22 | 72.40% |
| 2-1/2 | 63.5 | 3/8 | 9.53 | 3.16 | 75.60% |
| 2-1/2 | 63.5 | 5/16 | 7.94 | 2.24 | 79.00% |
| 2-1/2 | 63.5 | .283 | 7.19 | 1.85 | 80.70% |
| 2-1/2 | 63.5 | .263 | 6.68 | 1.61 | 81.90% |
| 2-1/2 | 63.5 | .250 | 6.35 | 1.46 | 82.60% |
| 2-1/2 | 63.5 | .225 | 5.72 | 1.19 | 84.20% |
| 2-1/2 | 63.5 | .207 | 5.26 | 1.02 | 85.30% |
| 2-1/2 | 63.5 | .192 | 4.88 | .88 | 86.20% |
| 2-1/2 | 63.5 | .177 | 4.50 | .75 | 87.20% |
| 2-1/2 | 63.5 | .162 | 4.11 | .63 | 88.20% |
| 2-1/2 | 63.5 | .148 | 3.76 | .53 | 89.10% |
| 2-1/4 | 57.15 | 1 | 25.40 | 20.61 | 47.90% |
| 2-1/4 | 57.15 | 3/4 | 19.05 | 12.37 | 56.20% |
| 2-1/4 | 57.15 | 11/16 | 17.46 | 10.58 | 58.70% |
| 2-1/4 | 57.15 | 5/8 | 15.88 | 8.90 | 61.20% |
| 2-1/4 | 57.15 | 9/16 | 14.29 | 7.34 | 64.00% |
| 2-1/4 | 57.15 | 1/2 | 12.70 | 5.91 | 66.90% |
| 2-1/4 | 57.15 | 7/16 | 11.11 | 4.62 | 70.10% |
| 2-1/4 | 57.15 | 3/8 | 9.53 | 3.46 | 73.40% |
| 2-1/4 | 57.15 | 5/16 | 7.94 | 2.46 | 77.10% |
| 2-1/4 | 57.15 | .283 | 7.19 | 2.04 | 78.90% |
| 2-1/4 | 57.15 | .263 | 6.68 | 1.77 | 80.20% |
| 2-1/4 | 57.15 | .250 | 6.35 | 1.61 | 81.00% |
| 2-1/4 | 57.15 | .225 | 5.72 | 1.31 | 82.60% |
| 2-1/4 | 57.15 | .207 | 5.26 | 1.12 | 83.90% |
| 2-1/4 | 57.15 | .192 | 4.88 | .97 | 84.90% |
| 2-1/4 | 57.15 | .177 | 4.50 | .83 | 85.90% |
| 2-1/4 | 57.15 | .162 | 4.11 | .70 | 87.00% |
| 2-1/4 | 57.15 | .148 | 3.76 | .59 | 88.00% |
| 2-1/4 | 57.15 | .135 | 3.43 | .49 | 89.00% |
| 2 | 50.80 | 1 | 25.40 | 22.49 | 44.40% |
| 2 | 50.80 | 3/4 | 19.05 | 13.57 | 52.90% |
| 2 | 50.80 | 11/16 | 17.46 | 11.62 | 55.40% |
| 2 | 50.80 | 5/8 | 15.88 | 9.79 | 58.00% |
| 2 | 50.80 | 9/16 | 14.29 | 8.09 | 60.90% |
| 2 | 50.80 | 1/2 | 12.70 | 6.53 | 64.00% |
| 2 | 50.80 | 7/16 | 11.11 | 5.11 | 67.30% |
| 2 | 50.80 | 3/8 | 9.53 | 3.84 | 70.90% |
| 2 | 50.80 | 5/16 | 7.94 | 2.73 | 74.80% |
| 2 | 50.80 | .283 | 7.19 | 2.26 | 76.70% |
| 2 | 50.80 | .263 | 6.68 | 1.97 | 78.10% |
| 2 | 50.80 | .250 | 6.35 | 1.79 | 79.00% |
| 2 | 50.80 | .225 | 5.72 | 1.46 | 80.80% |
| 2 | 50.80 | .207 | 5.26 | 1.25 | 82.10% |
| 2 | 50.80 | .192 | 4.88 | 1.08 | 83.20% |
| 2 | 50.80 | .177 | 4.50 | .92 | 84.40% |
| 2 | 50.80 | .162 | 4.11 | .78 | 85.60% |
| 2 | 50.80 | .148 | 3.76 | .65 | 86.70% |
| 2 | 50.80 | .135 | 3.43 | .55 | 87.80% |
| 2 | 50.80 | .120 | 3.05 | .44 | 89.00% |

| | | | | | |
|-------|-------|-------|-------|-------|--------|
| 1-3/4 | 44.45 | 1 | 25.40 | 24.76 | 40.50% |
| 1-3/4 | 44.45 | 3/4 | 19.05 | 15.03 | 49.00% |
| 1-3/4 | 44.45 | 11/16 | 17.46 | 12.90 | 51.60% |
| 1-3/4 | 44.45 | 5/8 | 15.88 | 10.88 | 54.30% |
| 1-3/4 | 44.45 | 9/16 | 14.29 | 9.01 | 57.30% |
| 1-3/4 | 44.45 | 1/2 | 12.70 | 7.29 | 60.50% |
| 1-3/4 | 44.45 | 7/16 | 11.11 | 5.71 | 64.00% |
| 1-3/4 | 44.45 | 3/8 | 9.53 | 4.30 | 67.80% |
| 1-3/4 | 44.45 | 5/16 | 7.94 | 3.07 | 71.90% |
| 1-3/4 | 44.45 | .283 | 7.19 | 2.55 | 74.10% |
| 1-3/4 | 44.45 | .263 | 6.68 | 2.22 | 75.60% |
| 1-3/4 | 44.45 | .250 | 6.35 | 2.02 | 76.60% |
| 1-3/4 | 44.45 | .225 | 5.72 | 1.65 | 78.50% |
| 1-3/4 | 44.45 | .207 | 5.26 | 1.41 | 80.00% |
| 1-3/4 | 44.45 | .192 | 4.88 | 1.22 | 81.20% |
| 1-3/4 | 44.45 | .177 | 4.50 | 1.04 | 82.50% |
| 1-3/4 | 44.45 | .162 | 4.11 | .88 | 83.80% |
| 1-3/4 | 44.45 | .148 | 3.76 | .74 | 85.00% |
| 1-3/4 | 44.45 | .135 | 3.43 | .62 | 86.20% |
| 1-3/4 | 44.45 | .120 | 3.05 | .49 | 87.60% |
| 1-1/2 | 38.10 | 1 | 25.40 | 27.57 | 36.00% |
| 1-1/2 | 38.10 | 3/4 | 19.05 | 16.86 | 44.40% |
| 1-1/2 | 38.10 | 11/16 | 17.46 | 14.50 | 47.00% |
| 1-1/2 | 38.10 | 5/8 | 15.88 | 12.27 | 49.80% |
| 1-1/2 | 38.10 | 9/16 | 14.29 | 10.18 | 52.80% |
| 1-1/2 | 38.10 | 1/2 | 12.70 | 8.25 | 56.30% |
| 1-1/2 | 38.10 | 7/16 | 11.11 | 6.48 | 59.90% |
| 1-1/2 | 38.10 | 3/8 | 9.53 | 4.90 | 64.00% |
| 1-1/2 | 38.10 | 5/16 | 7.94 | 3.50 | 68.50% |
| 1-1/2 | 38.10 | .283 | 7.19 | 2.91 | 70.80% |
| 1-1/2 | 38.10 | .263 | 6.68 | 2.54 | 72.40% |
| 1-1/2 | 38.10 | .250 | 6.35 | 2.31 | 73.40% |
| 1-1/2 | 38.10 | .225 | 5.72 | 1.89 | 75.60% |
| 1-1/2 | 38.10 | .207 | 5.26 | 1.62 | 77.20% |
| 1-1/2 | 38.10 | .192 | 4.88 | 1.40 | 78.60% |
| 1-1/2 | 38.10 | .177 | 4.50 | 1.20 | 80.00% |
| 1-1/2 | 38.10 | .162 | 4.11 | 1.02 | 81.50% |
| 1-1/2 | 38.10 | .148 | 3.76 | .85 | 82.80% |
| 1-1/2 | 38.10 | .135 | 3.43 | .72 | 84.20% |
| 1-1/2 | 38.10 | .120 | 3.05 | .57 | 85.70% |
| 1-3/8 | 34.93 | 3/4 | 19.05 | 17.97 | 41.90% |
| 1-3/8 | 34.93 | 11/16 | 17.46 | 15.47 | 44.40% |
| 1-3/8 | 34.93 | 5/8 | 15.88 | 13.10 | 47.30% |
| 1-3/8 | 34.93 | 9/16 | 14.29 | 10.88 | 50.40% |
| 1-3/8 | 34.93 | 1/2 | 12.70 | 8.83 | 53.80% |
| 1-3/8 | 34.93 | 7/16 | 11.11 | 6.95 | 57.60% |
| 1-3/8 | 34.93 | 3/8 | 9.53 | 5.26 | 61.70% |
| 1-3/8 | 34.93 | 5/16 | 7.94 | 3.77 | 66.40% |
| 1-3/8 | 34.93 | .283 | 7.19 | 3.14 | 68.80% |
| 1-3/8 | 34.93 | .263 | 6.68 | 2.74 | 70.50% |
| 1-3/8 | 34.93 | .250 | 6.35 | 2.49 | 71.60% |
| 1-3/8 | 34.93 | .225 | 5.72 | 2.04 | 73.90% |
| 1-3/8 | 34.93 | .207 | 5.26 | 1.75 | 75.60% |
| 1-3/8 | 34.93 | .192 | 4.88 | 1.52 | 77.00% |
| 1-3/8 | 34.93 | .177 | 4.50 | 1.30 | 78.50% |
| 1-3/8 | 34.93 | .162 | 4.11 | 1.10 | 80.00% |
| 1-3/8 | 34.93 | .148 | 3.76 | .92 | 81.50% |
| 1-3/8 | 34.93 | .135 | 3.43 | .78 | 82.90% |
| 1-3/8 | 34.93 | .120 | 3.05 | .62 | 84.60% |

| | | | | | |
|-------|-------|-------|-------|-------|--------|
| 1-1/4 | 31.75 | 3/4 | 19.05 | 19.22 | 39.10% |
| 1-1/4 | 31.75 | 11/16 | 17.46 | 16.57 | 41.60% |
| 1-1/4 | 31.75 | 5/8 | 15.88 | 14.06 | 44.40% |
| 1-1/4 | 31.75 | 9/16 | 14.29 | 11.70 | 47.50% |
| 1-1/4 | 31.75 | 1/2 | 12.70 | 9.51 | 51.00% |
| 1-1/4 | 31.75 | 7/16 | 11.11 | 7.50 | 54.80% |
| 1-1/4 | 31.75 | 3/8 | 9.53 | 5.69 | 59.20% |
| 1-1/4 | 31.75 | 5/16 | 7.94 | 4.08 | 64.00% |
| 1-1/4 | 31.75 | .283 | 7.19 | 3.40 | 66.50% |
| 1-1/4 | 31.75 | .263 | 6.68 | 2.97 | 68.30% |
| 1-1/4 | 31.75 | .250 | 6.35 | 2.70 | 69.40% |
| 1-1/4 | 31.75 | .225 | 5.72 | 2.22 | 71.80% |
| 1-1/4 | 31.75 | .207 | 5.26 | 1.90 | 73.60% |
| 1-1/4 | 31.75 | .192 | 4.88 | 1.65 | 75.10% |
| 1-1/4 | 31.75 | .177 | 4.50 | 1.42 | 76.70% |
| 1-1/4 | 31.75 | .162 | 4.11 | 1.20 | 78.40% |
| 1-1/4 | 31.75 | .148 | 3.76 | 1.01 | 79.90% |
| 1-1/4 | 31.75 | .135 | 3.43 | .85 | 81.50% |
| 1-1/4 | 31.75 | .120 | 3.05 | .68 | 83.20% |
| 1-1/4 | 31.75 | .105 | 2.67 | .52 | 85.10% |
| 1-1/8 | 28.58 | 3/4 | 19.05 | 20.68 | 36.00% |
| 1-1/8 | 28.58 | 11/16 | 17.46 | 17.86 | 38.50% |
| 1-1/8 | 28.58 | 5/8 | 15.88 | 15.17 | 41.30% |
| 1-1/8 | 28.58 | 9/16 | 14.29 | 12.65 | 44.40% |
| 1-1/8 | 28.58 | 1/2 | 12.70 | 10.30 | 47.90% |
| 1-1/8 | 28.58 | 7/16 | 11.11 | 8.14 | 51.80% |
| 1-1/8 | 28.58 | 3/8 | 9.53 | 6.19 | 56.30% |
| 1-1/8 | 28.58 | 5/16 | 7.94 | 4.45 | 61.20% |
| 1-1/8 | 28.58 | .283 | 7.19 | 3.71 | 63.80% |
| 1-1/8 | 28.58 | .263 | 6.68 | 3.25 | 65.70% |
| 1-1/8 | 28.58 | .250 | 6.35 | 2.96 | 66.90% |
| 1-1/8 | 28.58 | .225 | 5.72 | 2.43 | 69.40% |
| 1-1/8 | 28.58 | .207 | 5.26 | 2.08 | 71.30% |
| 1-1/8 | 28.58 | .192 | 4.88 | 1.81 | 73.00% |
| 1-1/8 | 28.58 | .177 | 4.50 | 1.55 | 74.70% |
| 1-1/8 | 28.58 | .162 | 4.11 | 1.32 | 76.40% |
| 1-1/8 | 28.58 | .148 | 3.76 | 1.11 | 78.10% |
| 1-1/8 | 28.58 | .135 | 3.43 | .93 | 79.70% |
| 1-1/8 | 28.58 | .120 | 3.05 | .74 | 81.70% |
| 1-1/8 | 28.58 | .105 | 2.67 | .58 | 83.70% |
| 1-1/8 | 28.58 | .092 | 2.34 | .45 | 85.50% |
| 1 | 25.4 | 3/4 | 19.05 | 22.38 | 32.60% |
| 1 | 25.4 | 11/16 | 17.46 | 19.37 | 35.10% |
| 1 | 25.4 | 5/8 | 15.88 | 16.49 | 37.90% |
| 1 | 25.4 | 9/16 | 14.29 | 13.78 | 41.00% |
| 1 | 25.4 | 1/2 | 12.70 | 11.25 | 44.40% |
| 1 | 25.4 | 7/16 | 11.11 | 8.91 | 48.40% |
| 1 | 25.4 | 3/8 | 9.53 | 6.79 | 52.90% |
| 1 | 25.4 | 5/16 | 7.94 | 4.90 | 58.00% |
| 1 | 25.4 | .283 | 7.19 | 4.09 | 60.80% |
| 1 | 25.4 | .263 | 6.68 | 3.58 | 62.70% |
| 1 | 25.4 | .250 | 6.35 | 3.26 | 64.00% |
| 1 | 25.4 | .225 | 5.72 | 2.69 | 66.60% |
| 1 | 25.4 | .207 | 5.26 | 2.31 | 68.60% |
| 1 | 25.4 | .192 | 4.88 | 2.01 | 70.40% |
| 1 | 25.4 | .177 | 4.50 | 1.72 | 72.20% |
| 1 | 25.4 | .162 | 4.11 | 1.46 | 74.00% |
| 1 | 25.4 | .148 | 3.76 | 1.23 | 75.90% |
| 1 | 25.4 | .135 | 3.43 | 1.04 | 77.60% |
| 1 | 25.4 | .120 | 3.05 | .83 | 79.70% |
| 1 | 25.4 | .105 | 2.67 | .64 | 81.90% |
| 1 | 25.4 | .092 | 2.34 | .50 | 83.90% |
| 1 | 25.4 | .080 | 2.03 | .38 | 85.70% |

| | | | | | |
|-----|-------|------|-------|-------|--------|
| 7/8 | 22.23 | 5/8 | 15.88 | 18.06 | 34.00% |
| 7/8 | 22.23 | 9/16 | 14.29 | 15.13 | 37.00% |
| 7/8 | 22.23 | 1/2 | 12.70 | 12.38 | 40.50% |
| 7/8 | 22.23 | 7/16 | 11.11 | 9.84 | 44.40% |
| 7/8 | 22.23 | 3/8 | 9.53 | 7.52 | 49.00% |
| 7/8 | 22.23 | 5/16 | 7.94 | 5.44 | 54.30% |
| 7/8 | 22.23 | .283 | 7.19 | 4.55 | 57.10% |
| 7/8 | 22.23 | .263 | 6.68 | 3.99 | 59.10% |
| 7/8 | 22.23 | .250 | 6.35 | 3.64 | 60.50% |
| 7/8 | 22.23 | .225 | 5.72 | 3.01 | 63.30% |
| 7/8 | 22.23 | .207 | 5.26 | 2.58 | 65.30% |
| 7/8 | 22.23 | .192 | 4.88 | 2.25 | 67.20% |
| 7/8 | 22.23 | .177 | 4.50 | 1.93 | 69.20% |
| 7/8 | 22.23 | .162 | 4.11 | 1.64 | 71.20% |
| 7/8 | 22.23 | .148 | 3.76 | 1.38 | 73.50% |
| 7/8 | 22.23 | .135 | 3.43 | 1.17 | 75.10% |
| 7/8 | 22.23 | .120 | 3.05 | .93 | 77.30% |
| 7/8 | 22.23 | .105 | 2.67 | .72 | 79.70% |
| 7/8 | 22.23 | .092 | 2.34 | .56 | 81.90% |
| 7/8 | 22.23 | .080 | 2.03 | .43 | 83.90% |
| 3/4 | 19.05 | 5/8 | 15.88 | 19.98 | 29.70% |
| 3/4 | 19.05 | 9/16 | 14.29 | 16.79 | 32.60% |
| 3/4 | 19.05 | 1/2 | 12.70 | 13.79 | 36.00% |
| 3/4 | 19.05 | 7/16 | 11.11 | 11.00 | 39.90% |
| 3/4 | 19.05 | 3/8 | 9.53 | 8.44 | 44.40% |
| 3/4 | 19.05 | 5/16 | 7.94 | 6.13 | 49.80% |
| 3/4 | 19.05 | .283 | 7.19 | 5.15 | 52.70% |
| 3/4 | 19.05 | .263 | 6.68 | 4.52 | 54.80% |
| 3/4 | 19.05 | .250 | 6.35 | 4.12 | 56.30% |
| 3/4 | 19.05 | .225 | 5.72 | 3.41 | 59.20% |
| 3/4 | 19.05 | .207 | 5.26 | 2.93 | 61.40% |
| 3/4 | 19.05 | .192 | 4.88 | 2.56 | 63.40% |
| 3/4 | 19.05 | .177 | 4.50 | 2.20 | 65.50% |
| 3/4 | 19.05 | .162 | 4.11 | 1.87 | 67.60% |
| 3/4 | 19.05 | .148 | 3.76 | 1.58 | 69.80% |
| 3/4 | 19.05 | .135 | 3.43 | 1.33 | 71.80% |
| 3/4 | 19.05 | .120 | 3.05 | 1.07 | 74.30% |
| 3/4 | 19.05 | .105 | 2.67 | .83 | 76.90% |
| 3/4 | 19.05 | .092 | 2.34 | .65 | 79.30% |
| 3/4 | 19.05 | .080 | 2.03 | .50 | 81.70% |
| 5/8 | 15.88 | 9/16 | 14.29 | 18.87 | 27.70% |
| 5/8 | 15.88 | 1/2 | 12.70 | 15.57 | 30.90% |
| 5/8 | 15.88 | 7/16 | 11.11 | 12.47 | 34.60% |
| 5/8 | 15.88 | 3/8 | 9.53 | 9.61 | 39.10% |
| 5/8 | 15.88 | 5/16 | 7.94 | 7.03 | 44.40% |
| 5/8 | 15.88 | .283 | 7.19 | 5.91 | 47.40% |
| 5/8 | 15.88 | .263 | 6.68 | 5.20 | 49.50% |
| 5/8 | 15.88 | .250 | 6.35 | 4.76 | 51.00% |
| 5/8 | 15.88 | .225 | 5.72 | 3.94 | 54.00% |
| 5/8 | 15.88 | .207 | 5.26 | 3.40 | 56.40% |
| 5/8 | 15.88 | .192 | 4.88 | 2.97 | 58.50% |
| 5/8 | 15.88 | .177 | 4.50 | 2.56 | 60.70% |
| 5/8 | 15.88 | .162 | 4.11 | 2.18 | 63.10% |
| 5/8 | 15.88 | .148 | 3.76 | 1.85 | 65.40% |
| 5/8 | 15.88 | .135 | 3.43 | 1.56 | 67.60% |
| 5/8 | 15.88 | .120 | 3.05 | 1.25 | 70.30% |
| 5/8 | 15.88 | .105 | 2.67 | .98 | 73.40% |
| 5/8 | 15.88 | .092 | 2.34 | .76 | 76.00% |
| 5/8 | 15.88 | .080 | 2.03 | .58 | 78.60% |
| 5/8 | 15.88 | .072 | 1.83 | .48 | 80.40% |
| 5/8 | 15.88 | .063 | 1.60 | .37 | 82.50% |

| | | | | | |
|------|-------|------|-------|-------|--------|
| 1/2 | 12.70 | 1/2 | 12.70 | 16.96 | 25.00% |
| 1/2 | 12.70 | 7/16 | 11.11 | 14.42 | 28.40% |
| 1/2 | 12.70 | 3/8 | 9.53 | 11.19 | 32.70% |
| 1/2 | 12.70 | 5/16 | 7.94 | 8.24 | 37.90% |
| 1/2 | 12.70 | .283 | 7.19 | 6.96 | 40.80% |
| 1/2 | 12.70 | .263 | 6.68 | 6.14 | 42.90% |
| 1/2 | 12.70 | .250 | 6.35 | 5.62 | 44.40% |
| 1/2 | 12.70 | .225 | 5.72 | 4.68 | 47.50% |
| 1/2 | 12.70 | .207 | 5.26 | 4.04 | 49.80% |
| 1/2 | 12.70 | .192 | 4.88 | 3.54 | 52.20% |
| 1/2 | 12.70 | .177 | 4.50 | 3.06 | 54.50% |
| 1/2 | 12.70 | .162 | 4.11 | 2.61 | 57.10% |
| 1/2 | 12.70 | .148 | 3.76 | 2.22 | 59.50% |
| 1/2 | 12.70 | .135 | 3.48 | 1.88 | 62.00% |
| 1/2 | 12.70 | .120 | 3.05 | 1.51 | 65.00% |
| 1/2 | 12.70 | .105 | 2.67 | 1.18 | 68.30% |
| 1/2 | 12.70 | .092 | 2.34 | .93 | 71.30% |
| 1/2 | 12.70 | .080 | 2.03 | .71 | 74.30% |
| 1/2 | 12.70 | .072 | 1.83 | .58 | 76.40% |
| 1/2 | 12.70 | .063 | 1.60 | .45 | 78.90% |
| | | | | | |
| 7/16 | 11.11 | 7/16 | 11.11 | 15.40 | 25.00% |
| 7/16 | 11.11 | 3/8 | 9.53 | 12.20 | 29.00% |
| 7/16 | 11.11 | 5/16 | 7.94 | 9.03 | 34.00% |
| 7/16 | 11.11 | .283 | 7.19 | 7.64 | 36.90% |
| 7/16 | 11.11 | .263 | 6.68 | 6.75 | 39.00% |
| 7/16 | 11.11 | .250 | 6.35 | 6.19 | 40.50% |
| 7/16 | 11.11 | .225 | 5.72 | 5.16 | 43.60% |
| 7/16 | 11.11 | .207 | 5.26 | 4.47 | 46.00% |
| 7/16 | 11.11 | .192 | 4.88 | 3.92 | 48.30% |
| 7/16 | 11.11 | .177 | 4.50 | 3.40 | 50.70% |
| 7/16 | 11.11 | .162 | 4.11 | 2.90 | 53.20% |
| 7/16 | 11.11 | .148 | 3.76 | 2.47 | 55.80% |
| 7/16 | 11.11 | .135 | 3.43 | 2.09 | 58.40% |
| 7/16 | 11.11 | .120 | 3.05 | 1.69 | 61.50% |
| 7/16 | 11.11 | .105 | 2.67 | 1.33 | 65.00% |
| 7/16 | 11.11 | .092 | 2.34 | 1.04 | 68.30% |
| 7/16 | 11.11 | .080 | 2.03 | .80 | 71.50% |
| 7/16 | 11.11 | .072 | 1.83 | .66 | 73.70% |
| 7/16 | 11.11 | .063 | 1.60 | .51 | 76.40% |
| | | | | | |
| 3/8 | 9.53 | 3/8 | 9.53 | 13.20 | 25.00% |
| 3/8 | 9.53 | 5/16 | 7.94 | 9.99 | 29.70% |
| 3/8 | 9.53 | .283 | 7.19 | 8.48 | 32.50% |
| 3/8 | 9.53 | .263 | 6.68 | 7.51 | 34.50% |
| 3/8 | 9.53 | .250 | 6.35 | 6.89 | 36.00% |
| 3/8 | 9.53 | .225 | 5.72 | 5.77 | 39.00% |
| 3/8 | 9.53 | .207 | 5.26 | 5.00 | 41.50% |
| 3/8 | 9.53 | .192 | 4.88 | 4.39 | 43.80% |
| 3/8 | 9.53 | .177 | 4.50 | 3.82 | 46.10% |
| 3/8 | 9.53 | .162 | 4.11 | 3.27 | 48.70% |
| 3/8 | 9.53 | .148 | 3.76 | 2.79 | 51.40% |
| 3/8 | 9.53 | .135 | 3.43 | 2.37 | 54.10% |
| 3/8 | 9.53 | .120 | 3.05 | 1.92 | 57.40% |
| 3/8 | 9.53 | .105 | 2.67 | 1.51 | 61.00% |
| 3/8 | 9.53 | .092 | 2.34 | 1.18 | 64.50% |
| 3/8 | 9.53 | .080 | 2.03 | .91 | 67.90% |
| 3/8 | 9.53 | .072 | 1.83 | .75 | 70.40% |
| 3/8 | 9.53 | .063 | 1.60 | .59 | 73.30% |
| 3/8 | 9.53 | .054 | 1.37 | .44 | 76.40% |

| | | | | | |
|------|------|------|------|------|--------|
| 5/16 | 7.94 | .263 | 6.68 | 8.46 | 29.50% |
| 5/16 | 7.94 | .250 | 6.35 | 7.78 | 30.90% |
| 5/16 | 7.94 | .225 | 5.72 | 6.53 | 33.80% |
| 5/16 | 7.94 | .207 | 5.26 | 5.68 | 36.20% |
| 5/16 | 7.94 | .192 | 4.88 | 5.00 | 38.40% |
| 5/16 | 7.94 | .177 | 4.50 | 4.36 | 40.80% |
| 5/16 | 7.94 | .162 | 4.11 | 3.74 | 43.40% |
| 5/16 | 7.94 | .148 | 3.76 | 3.20 | 46.00% |
| 5/16 | 7.94 | .135 | 3.43 | 2.72 | 48.80% |
| 5/16 | 7.94 | .120 | 3.05 | 2.21 | 52.20% |
| 5/16 | 7.94 | .105 | 2.67 | 1.74 | 56.00% |
| 5/16 | 7.94 | .092 | 2.34 | 1.37 | 59.60% |
| 5/16 | 7.94 | .080 | 2.03 | 1.07 | 63.40% |
| 5/16 | 7.94 | .072 | 1.83 | .88 | 66.10% |
| 5/16 | 7.94 | .063 | 1.60 | .69 | 69.30% |
| 5/16 | 7.94 | .054 | 1.37 | .51 | 72.70% |
| | | | | | |
| 1/4 | 6.35 | .250 | 6.35 | 8.95 | 25.00% |
| 1/4 | 6.35 | .225 | 5.72 | 7.55 | 27.70% |
| 1/4 | 6.35 | .207 | 5.26 | 6.59 | 29.90% |
| 1/4 | 6.35 | .192 | 4.88 | 5.82 | 32.00% |
| 1/4 | 6.35 | .177 | 4.50 | 5.08 | 34.30% |
| 1/4 | 6.35 | .162 | 4.11 | 4.38 | 36.80% |
| 1/4 | 6.35 | .148 | 3.76 | 3.76 | 39.40% |
| 1/4 | 6.35 | .135 | 3.43 | 3.21 | 42.20% |
| 1/4 | 6.35 | .120 | 3.05 | 2.62 | 45.60% |
| 1/4 | 6.35 | .105 | 2.67 | 2.07 | 49.60% |
| 1/4 | 6.35 | .092 | 2.34 | 1.64 | 53.40% |
| 1/4 | 6.35 | .080 | 2.03 | 1.28 | 57.40% |
| 1/4 | 6.35 | .072 | 1.83 | 1.06 | 60.30% |
| 1/4 | 6.35 | .063 | 1.60 | .83 | 63.80% |
| 1/4 | 6.35 | .054 | 1.37 | .62 | 67.60% |
| 1/4 | 6.35 | .047 | 1.19 | .48 | 70.90% |
| | | | | | |
| 3/16 | 4.76 | .192 | 4.88 | 6.97 | 24.40% |
| 3/16 | 4.76 | .177 | 4.50 | 6.12 | 26.50% |
| 3/16 | 4.76 | .162 | 4.11 | 5.30 | 28.80% |
| 3/16 | 4.76 | .148 | 3.76 | 4.57 | 31.30% |
| 3/16 | 4.76 | .135 | 3.43 | 3.92 | 33.80% |
| 3/16 | 4.76 | .120 | 3.05 | 3.22 | 37.20% |
| 3/16 | 4.76 | .105 | 2.67 | 2.56 | 41.10% |
| 3/16 | 4.76 | .092 | 2.34 | 2.04 | 45.10% |
| 3/16 | 4.76 | .080 | 2.03 | 1.60 | 49.10% |
| 3/16 | 4.76 | .072 | 1.83 | 1.33 | 52.20% |
| 3/16 | 4.76 | .063 | 1.60 | 1.05 | 56.00% |
| 3/16 | 4.76 | .054 | 1.37 | .79 | 60.30% |
| 3/16 | 4.76 | .047 | 1.19 | .62 | 63.90% |
| 3/16 | 4.76 | .041 | 1.04 | .48 | 67.30% |
| | | | | | |
| 1/8 | 3.18 | .135 | 3.43 | 4.98 | 23.10% |
| 1/8 | 3.18 | .120 | 3.05 | 4.19 | 26.00% |
| 1/8 | 3.18 | .105 | 2.67 | 3.37 | 29.50% |
| 1/8 | 3.18 | .092 | 2.34 | 2.71 | 33.20% |
| 1/8 | 3.18 | .080 | 2.03 | 2.15 | 37.20% |
| 1/8 | 3.18 | .072 | 1.83 | 1.79 | 40.30% |
| 1/8 | 3.18 | .063 | 1.60 | 1.43 | 44.20% |
| 1/8 | 3.18 | .054 | 1.37 | 1.09 | 48.80% |
| 1/8 | 3.18 | .047 | 1.19 | .85 | 52.80% |
| 1/8 | 3.18 | .041 | 1.04 | .67 | 56.70% |
| 1/8 | 3.18 | .035 | .89 | .50 | 61.00% |
| 1/8 | 3.18 | .032 | .81 | .43 | 63.40% |